



ALK-7-FP-101 QUICK START INSTRUCTIONS



CAP MOUNT FOR VARIOUS APPLICATIONS.

Locate and separate the hammerhead bolts from the caps and insert into upper groove (detail 1). Place graphic over bolts (detail 2). Screw caps back onto bolts as shown.

