


Set Up Instructions

INFT-950M


Step 1: Open soft molded case and remove x2 vertical side frames with lights.




Step 2: Push sections together to complete each vertical side frame.



Step 3: Remove top and bottom horizontal frames.



Step 4: Join vertical side frames to top and bottom horizontal frames.



Step 5: Connect the base power cords on each side to vertical side frames.




Step 6: Complete electrical connections between sections on vertical side frames.




Set Up Instructions

INFT-950M

Step 7: Insert center support pole between vertical side frames. Frame build completed.



Step 8: Insert SEG graphic into 4 corners of frame by pressing silicone into frame edge.



Step 9: Work SEG graphic towards the center of each side by pressing silicone into edge of frame.



Step 10: Repeat for reverse side of frame.



Step 11: Twist feet to open position.



Step 12: Plug power supply into bottom of frame and stand in upright position.



Set Up Instructions

OPTIONAL: Unroll frame covers and slide them into the groove of the frame from top to bottom. For with one stand or on the outer two edges of multiple stands when connected together.



OPTIONAL: Connect frames together using the stands with the top of one frame to the bottom of another to create a continuous wall.

